


Optimum M4100



Screen Protector Installation



1 Turn the terminal off. Clean the display screen with a soft, slightly damp cloth. Remove screen protector from bag. Peel mask film off of screen protector face.



2 Install screen protector faced down onto the display screen. Slide tip of the screen protector into top gap of case. Bow screen protector slightly to allow bottom tip to slide into bottom gap of case.



3 Use your thumbs to slide the screen protector until it covers the screen and lays flat. Turn the terminal on.



Note To remove screen protector, attach a piece of adhesive tape to one corner and pull back gently. Discard used screen protector. See Step 1 for installation.

World Headquarters:
Hypercom Corporation | 2851 West Kathleen Road, Phoenix, Arizona 85053, USA
Tel: +1.602.504.5000 | Fax: +1.602.504.4655 | www.hypercom.com
© 2007, Hypercom Corporation. All rights reserved. 940513-007 Rev. A 04/07



NORTH AMERICA | CENTRAL AMERICA | LATIN AMERICA | ASIA/PACIFIC RIM | EUROPE | MIDDLE EAST | AFRICA